








32x



**A**

32x




**B**

12x




**C**

3x



**D**

3x



**E**


12x



6,3x13mm

**F**

4x



3 x 20 mm


**G**

4x




**H**

12x




4,0 x 35 **I**

16x




5 x 38 **L**

12x




3,5 x 25 mm


**M**




1




2




3




4




5




6




7




8




9







10




11



12



13

 $3x$ 

14

